
Oklawaha Greenway User Count

Time Period: Tuesday, October 23, 2018 2:00 P.M. – Tuesday, October 30, 2018 2:00 P.M.

Location: On the Oklawaha Greenway in Jackson Park near Johnson Ditch



(Image: Google Maps)

Equipment: EcoCounter Pyro Counter

The Pyro Counter is able to count bicyclists, pedestrians, skateboarders, rollerbladers, or anyone who passes within approximately 16.5 feet of the equipment. However, the device is unable to differentiate between the different users and simply counts them as general users.


Possible sources of error include facility-users walking side-by-side or very close to each other; this is likely to include people walking or running side-by-side, children being held by a parent or walking along side of them, or dense groups of users. It is unclear how many users are likely to have been missed due to these circumstances and there has been no effort to make up for this likely discrepancy.

Results


Total Users	453		
Users/Hour	2.7		
Peak 24-Hour Usage	119		
Peak Day	Tuesday		
Peak 2-Hour Period	55		
Peak 2-Hour Day & Time	Tuesday, 10/23, 2:00 – 4:00 PM		

Patterns of Use


The following chart illustrates the average use of the sidewalk at the count location. This includes both weekday and weekend data and has greater weekday representation.



The second chart illustrates the different pattern of usage between the weekday and weekend.



The third chart shows users/day.



Notes

21	22	23	24	25	26	27
*	2	*	*	11/1	11/1	
Clear Actual:	Hazy Actual:	Clear Actual:	Clear Actual:	Rain Actual:	Rain Actual:	Rain Actual:
56° 35° Ø in	63° 32° Ø in	65° 38°	67° 38° Ø in	54° 39° Ø.09 in	51° 41° 1.82 in	57° 46° Ø in
28	29	30	31	1	2	3
*	*	*	*			
Partly Cloudy	Clear	Clear	Mostly Sunny	Rain	Rain	
Actual:	Actual:	Actual:	Actual:	Actual:	Actual:	
68° 41°	62° 39°	66° 34°	74° 38°	69° 57°	61° 42°	
<i>o</i> in	<i>o</i> in	<i>o</i> 0 in	<i>o</i> 0 in	🖉 0.48 in	0 .3 in	

(Weather Underground)